ONFI Technical Errata

Errata ID	**004**
Affected Spec Ver.	**ONFI 2.1**
Corrected Spec Ver.	

Submission info

Name	Company	Date
Amber Huffman	Intel	03/13/2009

Description of the specification technical flaw (add space as needed)

In the definition of the Extended Parameter Page, there is a typo in the signature value. Specifically, the ASCII code for “S” for byte 3 should be 53h, not 54h. This erratum corrects the typo.

Description of the correction

Update bytes 2-5 in Table 43 of the Extended Parameter Page definition as shown:

Byte	O/M	Description
	Revision information and features block	
0-1	M	Integrity CRC
2-5	M	Extended parameter page signature Byte 0: 45h, “E” Byte 1: 50h, “P” Byte 2: 50h, “P” Byte 3: 53h ~~54h~~, “S”

Update section 5.6.2.2 on the Extended Parameter Page signature as shown:

This field contains the extended parameter page signature. When two or more bytes of the signature are valid, then it denotes that a valid copy of the extended parameter page is present.

Byte 2 shall be set to 45h.

Byte 3 shall be set to 50h.

Byte 4 shall be set to 50h.

Byte 5 shall be set to 53h ~~54h~~.

Disposition log

3/13/2009	Erratum captured.
5/5/2009	Erratum ratified.

Technical input submitted to the ONFI Workgroup is subject to the terms of the ONFI contributor’s agreement.