ONFI Technical Errata

Errata ID	**006**
Affected Spec Ver.	**ONFI 2.0**
Corrected Spec Ver.	

Submission info

Name	Company	Date
Amber Huffman	Intel	7/16/2008

Description of the specification technical flaw (add space as needed)

This erratum corrects the minimum values for the tJIT(per) parameter in the source synchronous data interface. The minimum values for the tJIT(per) parameter should be negative, based on the equations where tJIT(per) is used.

Description of the correction

Modify the tJIT(per) value in Table 35 in section 4.2.3 as shown:

Parameter	Mode 0		Mode 1		Mode 2		Mode 3		Unit
	50		30		20		15		ns
	~20		~33		~50		~66		MHz
	Min	Max	Min	Max	Min	Max	Min	Max	
tJIT(per)	-0.7	0.7	-0.7	0.7	-0.7	0.7	-0.6	0.6	ns

Table 35 Source Synchronous Timing Modes

Disposition log

7/16/2008	Erratum captured.
9/17/2008	Erratum ratified.

Technical input submitted to the ONFI Workgroup is subject to the terms of the ONFI contributor's agreement.